10

15

- 1 -

[ABSTRACT]

METHOD FOR CLEANING A NOZZLE PLATE

- 5 A method for cleaning a printhead wherein
 - a solvent is applied followed by wet brushing of the nozzle plate to loosen debris collected on the nozzle plate.
 - A cleaning solvent is applied which is removed by vacuum cleaning in order clean the plate. A movement of the cleaning solvent over the nozzle plate is provided.

Both steps can be combined using the brush between the application of a single cleaning solvent and the vacuum cleaning. The movement of solvent helps to clean the brush.

Different steps can be executed by a cleaning module having a relative translating movement to the head.

Fig. 3